

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,976,299 B2
APPLICATION NO. : 10/631147
DATED : December 20, 2005
INVENTOR(S) : Christopher Seigneur

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Figures:

Fig. 1, "39"... should be deleted;
Fig. 2, "226" and "242"... should be deleted;
Fig. 3B, "354"... should be deleted;
Fig. 4B, "454"... should be deleted;
Fig. 5, "522", "532", "542", "544", and "546"... should be deleted;
Fig. 6, "622", "632", "642" and "646"... should be deleted.


Col. 1, line 37 "...inlet 234, 236..." should read ---inlets 234, 236...--.

Col. 3, line 26 "...cross sectional-views..." should read ---cross-sectional views...--;
Col. 3, lines 40-41 "...tubular extension 350..." should read ---tubular extension of check valve 350...--;
Col. 3, line 45 "...extensions 350..." should read ---check valve 350...--;
Col. 4, line 5 "...under side 344..." should read ---underside 344...--;
Col. 4, line 58 "...under side 444..." should read ---underside 444...--;
Col. 4, line 66 "cross sectional-views..." should read ---cross-sectional views...--;
Col. 5, line 29 "...under side 644..." should read ---underside 644...--;
Col. 5, line 31 "...650',...." should read ---650', [boldface] ...--.

Col. 6, line 18 "...in lets..." should read ---inlets...--.

Signed and Sealed this

Twenty-ninth Day of May, 2007



JON W. DUDAS
Director of the United States Patent and Trademark Office